



Marking machine for ferrules

Manual or pneumatically driven machine for marking of ferrules (before swaging). The machine is suitable for ferrules from dia. 3/16" up to 2" and you can choose 2 or 3 row type holder and 3 or 4 mm type height. There is also a 8 numbered marking wheel available.

MarkMan II

Technical data:

Ferrules dimension	3/16" - 2"
Ferrules diameter outside	min. 13 mm - max. 85 mm
Air pressure	6 bar
Colour	Zinc plated

Dimensions :

Length	500 mm
Width (manual model)	200 mm
Width (pneum.model)	380 mm
Height	500 mm
Weight (manual model)	28 kg
Weight (pneum.model)	35 kg

Designation:


MarkMan II, manual
(excl. QC-adapter and type holders)
MarkMan II-P, pneumatic
(excl. QC-adapter and type holders)

Part number:

9031-10-01
9031-10-02

Accessories:

Type case (4x8x18mm for 9031-10-03/10-04)	9031-00-04
Type case (3x6x19mm for 9031-11-03/11-04)	9031-12-04
Type print holder 2 lines (4mm, 12 types)	9031-10-03
Type print holder 3 lines (4mm, 12 types)	9031-10-04
Type print holder 2 lines (3mm, 12 types)	9031-11-03
Type print holder 3 lines (3mm, 12 types)	9031-11-04
Type print holder special on customers request	9031-10-07
QC-adapter for type print holder 3 and 4mm	9031-10-05
Marking wheel, -8 wheel	9031-00-06
QC-adapter for marking wheel	9031-10-06



9031-10-02
pneumatic




9031-10-01
manual



One type case consists of:
AAABBCCDDEEEFFGGHHIIJJKK
LLLMMNNNOOOOPPQRRRSSSTT
UUUVVWXXYZ//...,1112222333344
445556667778889990000 and 20 pcs
of blanks.


9031-00-06



9031-10-06

9031-10-04/11-04

9031-10-03/11-03



9031-10-05